THUS

OXC-2076
Copy 8 of 8

10 August 1961

| | MEMORANDUM FOR : Chief, Materiel Staff, Development Projects Division |
|----------------|---|
| 25X | A SUBJECT : Planning for Support Aircraft in OXCART |
| 25X1 | l. I thought you might be interested in the figures which Colonel Geary was quoting at large during our visit last week as a helpful assist in planning for the whole spectrum of problems associated with the presence of numerous support aircraft in the Area. |
| 25X1/ | 2. Colonel Geary's figures as to numbers of aircraft to be positioned are as follows: |
| | 4 F-101's (possible RF versions) 1 F-104C (chase plane) 1 C-47 1 U-3A 2 T-33's 1 C-130 (required for engine and parts airlift) |
| 25X1A 25X1A | |
| 25X1 | A away kits for the four aircraft, with the understanding that no attempt would |
| 25X1/ 25X1/ | here as well that has no capability to support the F-101 |
| | 4. Kelly Johnson says that he will support the F-104C from his own man- power resources. By contrast Colonel Geary estimates that support for the F-101's will require the addition of 17 military slots. I assume this is on the basis of three or four man crews plus supervisory overhead. Kelly |

Approved For Release 2007/01/17 : CIARDP81B00879R001000060031-5

0XC-2076 Page 2

| indicated that he would require Colonel Geary's assistance in obtaining from Air Force parts as required to maintain the F-104, but in the case of depot level maintenance as in the instance of the F-101's, it was clearly implied that this work would be done elsewhere, presumably 25X1A |
|--|
| 5. As I see it, at this time we now have what amounts to a formal requirement for at least seven high performance jets utilizing JP-4 fuel, as well as a C-130 employing the same fuel. In light of this I wonder if our fuel storage capability for JP-4 is adequate. I have no idea of the fuel consumption on the 101's or the 130's, but with the frequency of flights I can imagine. Since the 101 is to be used as a training aircraft, do you feel that we now have adequate storage capability for JP-4? Perhaps we should kick this subject around before it is too late to put forth a change order on our required tankage. In this connection I also wonder if anyone is giving thought to the special fuel tanks which will be required, I assume, at those bases where the KC-135's operate in support of the A-12. If the Air Force has as much trouble with stainless steel tanks as we seem to have had, starting today to be concerned about the problem is barely early enough. You may have already mentioned this to Colonel Geary, however. I gather that you will be taking into account the above number of aircraft in the course of figuring the proper dimensions and thickness of the concrete pad required for the support aircraft parking area. I have no idea of what the comparative wheel loadings of these aircraft are, but I assume you are taking steps to secure this information in conjunction with |
| SIGNED. |

JAMES A. CUNNINGHAM, JR. Acting Chief, DPD-DD/P

Distribution:

- 1 DPD/MAT 2 ASST CH/DPD

- 3 AC/IPD 4 IPD/SPB 5 IPD/AIMIN
- 6 DPD/SO
- 7 C/DPD/DB 8 DPD/RI

DPD-DD/P: JACunningham, Jr./mg

| 自己想查古城中 問為。 | | |
|------------------|-----------------|-------|
| | | 25X1A |
| | <u>.</u> | |
| | | |
| gerand de les de | g grant and the | |

25X1A

25X1A